WÜLF

SHADOWLUX IR
ILLUMINATOR MANUAL

RESEARCH | DEVELOPMENT | PRECISION

#IAMWULF

WHAT'S IN THE BOX

- Wulf Shadowlux
- Wulf Battery Charger & Cable
- Remote Dimmer Switch
- 18650 3400 mah battery
- Picatinny Rail Mount

BATTERY INSTALLATION

1. Unscrew the rear end cap from the unit.

2. Place the fully charged battery into the main body of the torch.

3. Screw the rear end cap back on to the torch.

MOUNTING THE TORCH

1. Unscrew all of the screws on the mount provided.

2. Place the torch into the mount and tighten all of the screws up.

3. Attach the base of the mount to a Picatinny/Weaver system.

WÜLF

OPERATION

1. Once installed and mounted, firmly press the button on the rear of the torch to turn on. Repeat to turn the torch off.

2. Alternatively, install the Remote Dimmer Switch onto the back of the unit and turn the torch on via the switch you have placed on your rifle.

3. To adjust the brightness, turn the dial on the back of the torch OR lightly press the Remote Dimmer Switch.

4. To adjust the focus of the beam, turn the head clockwise/anticlockwise to your desired diameter.

CHANGING THE WAVELENGTH

To change the wavelength of IR or to change to white light, simply rotate the lever behind the ball head of the torch either clockwise or anticlockwise for to your desired preference.

WARNING:
Avoid looking directly into device when switched on.

WÜLF